

# Instructions for applying Liquid Lexatron

- 1) Using 2" masking tape, tape off the desired area to be 'lexxed'.

**NOTE: If taping off a square area, rounded corners are best for a resistance to peeling up over time. Also, a drip guard around the bottom is necessary to keep chemicals from contact with the tubes in any spot other than the desired area.**

- 2) Wipe with THF (TetraHydroFuran) until a shiny tacky surface is achieved.
- 3) Have the Liquid Lex, a paint brush, clean THF, and a rag (to wipe up any spills or drips) ready.
- 4) Wipe the cleaned area once again with THF and immediately apply one coat of Liquid Lex. Wait about five to six minutes and apply the next coat of Lexatron.  
**NOTE: THF is only used on the first coat. The lex will not stick to the urethane fabric if it is not wet with THF when the first coat is applied.**
- 5) Once six coats of Lex have been applied to the desired area, allow to dry for several hours. (I recommend at least two hours at 70 degrees Fahrenheit)
- 6) Slowly peel up the tape around the edges of the lexxed area. Using a razor blade carefully cut off any excess lex.
- 7) Sit back and enjoy your handy work.